

CAUTION

DATE 21-3-18 SITE Fonterra / Dometts
FLEET 530 REGO MA T8894/5301

WHEEL NUTS ON THIS VEHICLE WERE REMOVED AT

0 0 0 0 0 0 km.

WHEEL NUTS MUST BE CHECKED WITHIN 50KM AND RETORQUED AT APPROX 100KM

Torque Setting Applied: 4 5 0 ft/lb or Nm

Signed & fitted by: Negan

Job Card Serial No. 103301

PRIME MOVER

<u>1</u>	<u>3</u>	<u>5</u>	<u>9</u>
		<u>6</u>	<u>10</u>
FRONT STEER	2ND STEER	FRONT DRIVE	REAR DRIVE
		<u>7</u>	<u>11</u>
<u>2</u>	<u>4</u>	<u>8</u>	<u>12</u>

TRAILER

<u>17</u>	<u>21</u>	<u>25</u>	<u>29</u>	<u>33</u>
<u>18</u>	<u>22</u>	<u>26</u>	<u>30</u>	<u>34</u>
1ST AXLE	2ND AXLE	3RD AXLE	4TH AXLE	5TH AXLE
<u>19</u>	<u>23</u>	<u>27</u>	<u>31</u>	<u>35</u>
<u>20</u>	<u>24</u>	<u>28</u>	<u>32</u>	<u>36</u>

RETORQUE km.

DATE

Signed & retorqued by: