ACAUTION

DATE 9	-4-18	SITE	Domets		
FLEET		REGO		T8900	
	IEEL MUTS ON		53° 5		
WHEEL NUTS ON THIS VEHICLE WERE REMOVED AT					
			△ km.		
WHEEL NUTS MUST BE CHECKED WITHIN 50KM AND RETORQUED AT APPROX 100KM					
Torque Setting Applied:	45 oft/	Signe	d &	22	
Setting Applied:		lb or Nm fitted	by: 190		
Job Card Serial No. 103304					
Job Card Serial No. 103304					
<u> </u>	PRIME MOVER		TRAILER		
1	3 5 9	VI	21 25 29	33	
	6 10	18	22 26 30	34	
EER	ER IVE VE	LL)			
TS 1	ZND STEER RONT DRIVE REAR DRIVE	IST AXLE	2ND AXLE 3RD AXLE 4TH AXLE	5ТН АХ LЕ	
FRONT STEER	2ND STEER FRONT DRIVE REAR DRIVE	15T	2ND 3RD 4TH	5TH	
	7 11	19	D3 77 31	35	
2	4 8 12	20	24 28 32		
2	4 0 12	20	44 20 92	36	
RETORQUE				DATE	
			km. Signed 8		
		retorqued by			