

Transport Maintenance (3rd Ave) Ltd.

Cnr 3rd Ave & Glasgow St Tauranga

Job 3679

Service Department
(07) 577 9895

PO Box 2270 / 23679
Fax (07) 578 8249

Parts Department
(07) 578 9418

MAKE B. Train MODEL Rear CHASSIS 23009

DATE 8-11-11 REGO --- MILEAGE ---

NAME DOM RT.T. JOB 99894 SIGNATURE ---

Station A3 | 100 100 100 | **Station A4**

A3	153	153
B3	144	144
C3	27	D _m 8 =

CAMBER: $\oplus 30'$

TYRE WEAR: Inner | Outer

Diagram labels: C/D 0.8, C/D 0.8, TOE-IN, TOE-OUT

A4	158	158
B4	150	150
C4	28	D _m 8 =

CAMBER: $\oplus 32'$

TYRE WEAR: Inner | Outer

Station B3 | 100 100 100 | **Station A4**

A5	155	155
B5	150	150
C5	29	D _m 8 =

CAMBER: $\oplus 30'$

TYRE WEAR: Inner | Outer

Diagram labels: C/D 0.6, C/D 0.7, TOE-IN, TOE-OUT

A6	157	157
B6	152	152
C6	26	D _m 8 =

CAMBER: $\oplus 29'$

TYRE WEAR: Inner | Outer

Station A3 | 100 100 100 | **Station A4**

A3	158	158
B3	152	152
C3	26	D _m 8 =

CAMBER: $\oplus 35'$

TYRE WEAR: Inner | Outer

Diagram labels: C/D 0.7, C/D 0.5, TOE-IN, TOE-OUT

A4	169	157
B4	150	151
C4	29	D _m 8 =

CAMBER: $\oplus 30'$

TYRE WEAR: Inner | Outer

Station B3 | 100 100 100 | **Station A4**

A5		
B5		
C5	+	D _m 8 =

CAMBER: +

TYRE WEAR: Inner | Outer

Diagram labels: C/D, C/D, TOE-IN, TOE-OUT

A6		
B6		
C6	+	D _m 8 =

CAMBER: +

TYRE WEAR: Inner | Outer