

Transport Maintenance (3rd Ave) Ltd.

Cnr 3rd Ave & Glasgow St Tauranga

Job # 3687
1015

Service Department
(07) 577 9895

PO Box 2270
Fax (07) 578 8249

o/n 3687
1023015

Parts Department
(07) 578 9418

MAKE Trailar MODEL H AXLE CHASSIS

DATE 9-12-11 REGO MILEAGE

NAME DOMETT JOB 10029 SIGNATURE

A3	141	140
B3	10	
C3	7	D=5 =

CAMBER
⊕ 30

TYRE WEAR
Outer Inner

A4	128	127
B4	125	12
C4	33	D=5 =

CAMBER
⊕ 30

TYRE WEAR
Inner Outer

A5	137	138
B5	12	136
C5	5	D=5 =

CAMBER
⊕ 30

TYRE WEAR
Outer Inner

A6	118	121
B6	126	12
C6	5	D=5 =

CAMBER
⊕ 25

TYRE WEAR
Inner Outer

A3	137	130
B3	11	150
C3	2	D=6 =

CAMBER
⊕ 25

TYRE WEAR
Outer Inner

A4	130	128
B4	120	12
C4	10	D=6 =

CAMBER
⊕ 25

TYRE WEAR
Inner Outer

A5	140	143
B5	14	137
C5	1	D=6 =

CAMBER
⊕ 30

TYRE WEAR

A6	120	136
B6	132	13
C6	12	D=6 =

CAMBER
⊕ 30

TYRE WEAR
Inner Outer