

Transport Maintenance (3rd Ave) Ltd.

Cnr 3rd Ave & Glasgow St Tauranga Job 3881

Service Department
(07) 577 9895

PO Box 2270
Fax (07) 578 8249


Parts Department
(07) 578 9418

MAKE *Truck* MODEL *S. Arle* CHASSIS *J.P. Haulage*


DATE *13/12/12* REGO *---* MILEAGE *---*

NAME *Donett* JOB *12172* SIGNATURE *---*

A1	
B1	
C1	+ :Dm =
CAMBER	
+	
-	
TYRE WEAR	
Outer Inner	



A2	
B2	
C2	+ :Dm =
CAMBER	
+	
-	
TYRE WEAR	
Inner Outer	



115
138
175

A3	136
B3	135
C3	1 :Dm 5 =
CAMBER	
⊕ 20'	
TYRE WEAR	
Outer Inner	


A4	123
B4	128
C4	5 :Dm 2 =
CAMBER	
⊕ 15	
TYRE WEAR	
Inner Outer	

102
130
+32

A5	140
B5	139
C5	1 :Dm 5 =
CAMBER	
⊕ 18	
TYRE WEAR	
Outer Inner	

100
170
-30

A6	124
B6	121
C6	5 :Dm 3 =
CAMBER	
⊕ 18	
TYRE WEAR	
Inner Outer	



Transport Maintenance (3rd Ave) Ltd.

Cnr 3rd Ave & Glasgow St Tauranga Job 3881

Service Department
(07) 577 9895

PO Box 2270
Fax (07) 578 8249

Parts Department
(07) 578 9418


MAKE *Trail* MODEL *5 PXL* CHASSIS *T.D. Haulage*

DATE *13-12-12* REGO MILEAGE

NAME *Dom ET* JOB *12172* SIGNATURE

*164
150
+14*

A1	176
B1	156
C1	25 : Dm 6 =
CAMBER	
⊕ 20	
TYRE WEAR	
Outer	Inner




A2	151
B2	161
C2	10 : Dm 6 =
CAMBER	
⊕ 20	
TYRE WEAR	
Inner	Outer

*190
170
-20*

*159
160
-1*

A3	162
B3	160
C3	22 : Dm 6 =
CAMBER	
⊕ 15	
TYRE WEAR	
Outer	Inner




A4	151
B4	161
C4	10 : Dm 6 =
CAMBER	
⊕ 20	
TYRE WEAR	
Inner	Outer

*150
140
-6*

*150
160
-10*

A5	165
B5	156
C5	9 : Dm 6 =
CAMBER	
+	
TYRE WEAR	
Outer	Inner



A6	150
B6	160
C6	10 : Dm 6 =
CAMBER	
+	
TYRE WEAR	
Inner	Outer

*160
150
+10*

