

Transport Maintenance (3rd Ave) Ltd.

Cnr 3rd Ave & Glasgow St Tauranga

Service Department
(07) 577 9895

o/n 39140

PO Box 2270
Fax (07) 578 8249

23113


Parts Department
(07) 578 9418

MAKE *Trailer* MODEL *5 AXLE* CHASSIS

DATE *27-11-12* REGO MILEAGE


NAME *DOMETT* JOB *12102* SIGNATURE

A ₁	
B ₁	
C ₁ ± : D _m =	
CAMBER	
+	
-	
TYRE WEAR	
Outer Inner	




A ₂	
B ₂	
C ₂	
CAMBER	
+	
-	
TYRE WEAR	
Inner Outer	

A ₃	<i>131</i>	<i>121</i>
B ₃	<i>130</i>	<i>115</i>
C ₃ ± : D _m =		
CAMBER		
⊕ 30		
TYRE WEAR		
Outer Inner		




A ₄	<i>132</i>	<i>142</i>
B ₄	<i>129</i>	<i>114</i>
C ₄		
CAMBER		
⊕ 15		
TYRE WEAR		
Inner Outer		

A ₅	<i>138</i>	
B ₅	<i>137</i>	
C ₅ ± : D _m =		
CAMBER		
⊕ 30		
TYRE WEAR		
Outer Inner		



A ₆	<i>128</i>	<i>128</i>
B ₆	<i>128</i>	<i>128</i>
C ₆		
CAMBER		
⊕ 15		
TYRE WEAR		
Inner Outer		



Transport Maintenance (3rd Ave) Ltd.

Cnr 3rd Ave & Glasgow St Tauranga

Service Department
(07) 577 9895

PO Box 2270
Fax (07) 578 8249

Parts Department
(07) 578 9418

MAKE... *Tristar* ... MODEL... *S. AXLE* ... CHASSIS.....

DATE... *27-11-12* ... REGO..... MILEAGE.....


NAME... *DOMETT* ... JOB... *12102* ... SIGNATURE.....

110
160
-50

A ₁	140
B ₁	170
C ₁	10 : D ₁ 8 =

CAMBER
⊕ 20

TYRE WEAR	
Outer	Inner



A ₂	120	A ₂	146
B ₂	131	B ₂	105
C ₂		141	

⊕ 10 : D₂ 8 =

CAMBER
⊕ 10


TYRE WEAR	
Inner	Outer

139
130
+9

A ₃	139
B ₃	130
C ₃	9 : D ₃ 8 =

CAMBER
⊕ 20

TYRE WEAR	
Outer	Inner



A ₄	125	A ₄	125
B ₄	132	B ₄	132
C ₄		7	

⊕ 10 : D₄ 8 =

CAMBER
⊕ 10


TYRE WEAR	
Inner	Outer

30
150
-120

A ₅	130
B ₅	130
C ₅	- : D ₅ 8 =

CAMBER
⊕ 20

TYRE WEAR	
Outer	Inner



A ₆	120	A ₆	220
B ₆	132	B ₆	103
C ₆		119	

⊕ 10 : D₆ 8 =

CAMBER
⊕ 10

TYRE WEAR	
Inner	Outer

