

vtnz CERTIFICATION CHECK SHEET

No. 18486924

DETAILS	Inspection Location <u>VT142</u>	Date <u>23/3/17</u>	Receipt No. <u>16807648</u>	Sale I.D. <u>EC HT</u>
	Name of Applicant <u>Donett</u>	Telephone		Border Checked YES NO
	Address	WOF Label		
	Order No. <u>4718</u>	LTS4085 No.		Authority No.
Hubmeter No. <u>12645</u>	Hubmeter Reading <u>1</u>		Expiry <u>1</u> / <u>1</u>	

VIN & ATTRIBUTES	VIN	<u>7A9E10017HA023570</u>										ATTACH VIN LABEL HERE	
	Chassis											Reference <u>1956</u>	
	Vehicle Type	<u>2</u>	N/U/R or S <u>N</u>										Border Check Date
	1st NZ Reg.											Engine No.	
	Prev. Country											Seats	
	Basic Colour	<u>SILVER</u>										Second Colour	
	Make	<u>DOMESTIC</u>										Model <u>EL001</u>	
	Sub Model											Variant	
	Veh Year	<u>2017</u>	Body Type	<u>TO</u>								Imported LHD <u>NO</u>	
	GVM	<u>30000</u>	CC Rating									Altern Fuel	
	Assembly Type	<u>2</u>											Odo Unit
	Class	<u>TO</u>											Orig. Country <u>NZL</u>
	Test Regime		FC Urban									FC Combined	
	A/C Fitted	<u>NO</u>											Special Permits
	Gas Type											TARE <u>6520</u>	Certifier ID <u>TDJAV</u>
VIN: Plate Made	<u>Checked</u>		<u>Etched</u>							<u>Checked</u>			
Attached	<u>Checked</u>		<u>Stamped</u>							<u>Checked</u>			
Valid Vin	<u>✓</u>												

REQUIRED DOCUMENTS	Detailed Registration Certificate	Statement of Compliance	Proof of Ownership
	Export/Dereg Certificate	Comp: ADR/EEC/ECE/FMVSS	LHD Declaration
	Completion Certificate	LVVTA Compliance Certificate	Structural Repair Certificate
	SSBELTSOK Plate Fitted	TDN/Singapore Compliance Exemption	Weighbridge Docket <u>✓</u>
	Repair Certificate Required	Y / N	Immigrants/Special Interest Vehicles

NZ Standards: 5413 5444 5446 5450 5451 5467 NZHVBC other _____

	Pass / Fail	Inspector ID	Fault Code	Items For Immediate Attention
Rear View Mirrors	<u>P</u>	<u>DM</u>		
Interior	<u>P</u>			
Steering & Suspension	<u>P</u>			
Seatbelts	<u>P</u>			
Glazing	<u>P</u>			
Lighting	<u>P</u>			
Tyres & Rims	<u>P</u>			
Braking System	<u>P</u>			
Misc	<u>P</u>			
Vehicle Structure	<u>P</u>			

VTNZ Malene St
23 MAR 2017
VT142



VEHICLES MUST BE RECHECKED WITHIN 20 WORKING DAYS OR ANOTHER COMPLETE INSPECTION CARRIED OUT

Initial Inspection	<u>DM</u>	<u>PASS</u> / FAIL	Recheck Inspection	PASS / FAIL
Insp. ID	<u>DM 23' 3 '17</u>		Insp. ID	/ /
Signature	<u>DM</u>		Signature	