

# vtnz CERTIFICATION CHECK SHEET

No. 18486932

69694

DETAILS	Inspection Location	Date	3-4-17	Receipt No.	8560504	Sale I.D.	ECHT
	Name of Applicant	Domett Trucks & Trailer					
	Address	c/- FONTERRA COOP LTD HAMILTON.			Telephone		
	Order No.	4719	LTS4085 No.		NAB0512		
Hubmeter No.	S-12520	Hubmeter Reading	6320		Authority No.		
						Expiry	1 / 1

VIN & ATTRIBUTES	VIN	7A9E10019H1023571						ATTACH VIN LABEL HERE
	Chassis	9H1023571			Reference	1964		
	Vehicle Type	02 TRAILER		(N)U/R or S	NEW		Border Check Date	
	Ist NZ Reg.				Engine No.	---		
	Prev. Country				Ist Reg Date			
	Basic Colour	SILVER			Seats	---		
	Make	DOMETT			Second Colour	BLUE		
	Sub Model	SAXLE TANKER			Model	E1001		
	Veh Year	2017	Body Type	TD	Variant	---		
	GVM	30000	CC Rating	---	Imported LHD	NO		
	Assembly Type	2 NZ BUILT			Engine Type	---		
	Class	TD TRAILER		No. Of Axles	5		Altern Fuel	---
	Test Regime	---	FC Urban	---	FC Ext. Urban	---		
	A/C Fitted	NO			FIS	NO		
	Gas Type	---			TARE	6320		Certifier ID
VIN: Plate Made	Checked			Etched			Checked	
Attached	Checked			Stamped	✓		Checked	TGSB1
Valid Vin	✓	TGSB1						

REQUIRED DOCUMENTS	Detailed Registration Certificate	Statement of Compliance	Proof of Ownership
	Export/Dereg Certificate	Compl: ADR/EEC/ECE/FMVSS	LHD Declaration
	Completion Certificate	LVVTA Compliance Certificate	Structural Repair Certificate
	SSBELTSOK Plate Fitted	TDN/Singapore Compliance Exemption	Weighbridge Docket
	Repair Certificate Required	Y / N	Immigrants/Special Interest Vehicles

NZ Standards: 5413  5444  5446  5450  5451  5467  NZHVBC  other \_\_\_\_\_

Pass / Fail	Inspector ID	Fault Code	Items For Immediate Attention
P F			
P F			
P F	TGSB1		
P F			
P F			
P F			
P F			
P F			
P F			
P F			
P F			

ENTERED



VEHICLES MUST BE RECHECKED WITHIN 20 WORKING DAYS OR ANOTHER COMPLETE INSPECTION CARRIED OUT

Initial Inspection	PASS / FAIL	Recheck Inspection	PASS / FAIL
Insp. ID	TGSB1 04/04/17	Insp. ID	/ /
Signature	<i>[Signature]</i>	Signature	