

vtnz CERTIFICATION CHECK SHEET

No. 18521446

DETAILS	Inspection Location <u>VT142</u> Date <u>30/6/17</u> Receipt No. <u>8565348</u> Sale I.D. <u>ECHT</u>
	Name of Applicant <u>Domett</u> Telephone _____
	Address <u>FONTERIA CO-OP GROUP HAMILTON</u>
	Order No. <u>4733</u> LTSA4085 No. <u>NAB2316</u>
	Hubmeter No. <u>51156</u> Hubmeter Reading <u>9KMS DATA-TRAC</u>

VIN & ATTRIBUTES	VIN <u>7A9E10014H1023588</u> ATTACH VIN LABEL HERE
	Chassis <u>1023588</u> Reference <u>1004-5</u>
	Vehicle Type <u>02 TRAILER</u> N/U/R or S <u>NEW</u> Border Check Date _____
	1st NZ Reg. _____ Engine No. _____
	Prev. Country _____ 1st Reg Date _____ Seats _____
	Basic Colour <u>SILVER</u> Second Colour <u>BLUE</u>
	Make <u>DOMETT</u> Model <u>E1001</u>
	Sub Model <u>5 AXLE TANKER</u> Indust Model _____ Variant _____
	Veh Year <u>2017</u> Body Type <u>TD</u> Imported LHD <u>NO</u>
	GVM <u>30000</u> CC Rating _____ Engine Type _____ Altern Fuel _____
	Assembly Type <u>2 NZ BUILT</u> Odometer _____ Odo Unit _____
	Class <u>TD TRAILER</u> No. Of Axles <u>5</u> Orig. Country <u>NZL</u>
	Test Regime _____ FC Urban _____ FC Ext. Urban _____ FC Combined _____
	A/C Fitted <u>NO</u> FIS <u>NO</u> Special Permits _____
	Gas Type _____ TARE <u>6360</u> Certifier ID <u>TGSBI</u>

DOCUMENTS	Detailed Registration Certificate	Statement of Compliance	Proof of Ownership
	Export/Dereg Certificate	Compl: ADR/EEC/ECE/FMVSS	LHD Declaration
	Completion Certificate	LVVTA Compliance Certificate	Structural Repair Certificate
	SSBELTSOK Plate Fitted	TDN/Singapore Compliance Exemption	Weighbridge Docket
	Repair Certificate Required	Y / N Immigrants/Special Interest Vehicles	TSL <u>0209813</u> ✓

NZ Standards: 5413 5444 5446 5450 5451 5467 NZHVC other _____

	Pass / Fail	Inspector ID	Fault Code	Items For Immediate Attention
Rear View Mirrors	P F			RECO # 7K774
Interior	P F			
Steering & Suspension	P F	<u>TGSBI</u>		
Seatbelts	P F			
Glazing	P F			
Lighting	P F			
Tyres & Rims	P F			
Braking System	P F			
Misc	P F			
Vehicle Structure	P F			

Appointed by
 NZ TRANSPORT AGENCY
 WAKA KOTAHU

VEHICLES MUST BE RECHECKED WITHIN 20 WORKING DAYS OR ANOTHER COMPLETE INSPECTION CARRIED OUT

Initial Inspection	<u>PASS</u> / FAIL	Recheck Inspection	PASS / FAIL
Insp. ID <u>TGSBI 30/06/2017</u>		Insp. ID / /	
Signature <u>[Signature]</u>		Signature	

Customer Conv