## **ACAUTION**

DATE 5-9-18	SITE REGO 533	Donet 10 T89 Z5
FLEET		
WHEEL NUTS ON THIS VEHICLE WERE REMOVED AT		
		O <sub>km</sub> .
WHEEL NUTS MUST BE CHECKED WITHIN 50KM AND RETORQUED AT APPROX 100KM		
Torque Setting Applied: 450	Signed & ft/lb or Nm fitted by:	Maa
Setting Applied.	TO BOT WITH TILLED BY.	
Job Card Serial No. 103335		
PRIME MOVER		TRAILER
1 3 5	9 17/2	A 25 29 33
	10 18 2	/\-\-\-\-\-\-\-\-\-\-\-\-\-\-\-\-\-\-\-
	10	2 20 30 34
TEE! EER	RIVE	XLE XLE
FRONT STEER 2ND STEER FRONT DRIVE	REAR DRIVE	2ND AXLE 3RD AXLE 5TH AXLE
FRO 2N FRO	RE,	
7	11 19	23 27 31 35
2 4 8	12 20 3	24 28 32 36
RETORQUE	kr	DATE
Signed &		
	retorqued by:	