

New Zealand Government

Heavy vehicle specialist certificate

Must be presented to a CoF (heavy) inspecting organisation

Heavy vehicle specialist inspector and inspecting organisation.

Version No. 06/16

Heavy vehicle specialist inspector's or manufacturing in	nspecting organisat				ispecting organisation	
GEORGE BARBOUR				GRB4		
Vehicle registration (optional)	VIN/chassis number					
	7 A 9 E	2 0	0 1 1 J	1 0	2 3 7 7 6	
Make 2018 DOMETT	Component being	certified:	√ Chassis		Load anchorage	
Model (optional) E2001-PH	Log bolsters		Towing conn	ection	Brakes	
Certification category	SRT		PSV stability		PSV rollover	
HVEC	Swept path		PBS			
Description of work						
DOMETT.						
Code/standard/rule certified to		Componer	nt load rating(s)			
HEAVY VEHICLES 2004 RULE 31002			CHASSIS GVM 33,000kg			
General drawing number(s)			AXLE RATING 10,432kg			
3322-05 C-E2001-SL			SUSPENSION RATING 10,432kg			
PROMECH CALCULATIONS 4- Special conditions (optional) THIS CERTIFICATE IS A STATEMENT OF COMPLIANCE AT I WARRANTY WITH RESPECT TO THE WORK CERTIFIED OR LAND TRANSPORT NZ APPROVED HEAVY VEHICLE SPECI.	THE TIME OF CERTIFIC ANY OTHER ASPECT	CATION ONLY / OF THIS VEHIO	AND DOES NOT OFFE	R OR IMPLY	ANY GUARANTEE OR D BE RE-INSPECTED BY A	
CERTIFICATION IS NULL & VOID IF VEHICLE/COMPONENT	IS SUBSEQUENTLY M					
Certification expiry date (if applicable) 07-08-2028	or	Hubodome	ter reading (whicheve	er comes first)		
Declaration		Designer's	ID (if different from inspi	ector below)	1	
I the undersigned, declare that I am the heavy vehicle specialist inspector identified and I hold a current valid appointment. I certify that the above mentioned vehicle component's design, manufacture and installation, and this certification complies in all respects with the Land Transport Rule: Vehicle Standards Compliance 2002 and my appointment. To the best of my knowledge the information contained in the certificate is true and correct.		Inspector's signature Inspector's name (PRINT IN CAPS) GEORGE BARBOUR Date Number 07-08-2018 A 5192				
	oF vehicle inspector			ate		

Form ID