

# Transport Maintenance (3rd Ave) Ltd.

Cnr 3rd Ave & Glasgow St, Tauranga

PO Box 2270

Ph. (07) 577 9895

Fax (07) 578 8249



measurements before aligning.

23853

Reg.nr ..... Type Low Loader ..... Miles/Km ..... Dat. 24/11/09


Name Dom ETT ..... Inv. no. 95363 ..... Sign. ....

A <sub>1</sub>	190	127
B <sub>1</sub>	189	203
C <sub>3</sub>	±1	:D <sub>m</sub> 4 =

CAMBER	
+	20'


A <sub>1</sub>	192	146
B <sub>1</sub>	191	190
C <sub>5</sub>	±1	:D <sub>m</sub> 4 =

CAMBER	
+	20



210	194	A <sub>2</sub>
180	193	B <sub>2</sub>
130	-D <sub>m</sub> 4	:±1 C <sub>4</sub>

CAMBER	
+	20'




140	193	A <sub>2</sub>
192	192	B <sub>2</sub>
130	-D <sub>m</sub> 4	:±1 C <sub>6</sub>

CAMBER	
+	25



A <sub>1</sub>	189	189
B <sub>1</sub>	185	185
C <sub>3</sub>	±3	:D <sub>m</sub> 6 =

CAMBER	
+	15'




200	200	A <sub>2</sub>
199	199	B <sub>2</sub>
130	-D <sub>m</sub> 6	:±1 C <sub>4</sub>

CAMBER	
+	20'

A <sub>1</sub>	195	193
B <sub>1</sub>	194	195
C <sub>5</sub>	±4	:D <sub>m</sub> 6 =

CAMBER	
+	20'



145	190	A <sub>2</sub>
188	189	B <sub>2</sub>
130	-D <sub>m</sub> 6	:±1 C <sub>6</sub>

CAMBER	
+	20