

Transport Maintenance (3rd Ave) Ltd.

Cnr 3rd Ave & Glasgow St, Tauranga

PO Box 2270

Ph. (07) 577 9895

Fax (07) 578 8249

() measurements before aligning.

o/n 3544

Reg.nr _____ Type 4 AXLE STOCK Miles/Km _____ Dat. 17-5-11


Name DOMETT Inv. no. 98823 Sign. _____

A ₁	130	121
B ₁	134	143
C ₃	24	22
:D _m 4 =		

CAMBER	
+	20
-	


A ₁	170	139
B ₁	170	125
C ₅		14
:D _m 4 =		

CAMBER	
+	25
-	



A ₂	125	135
B ₂	171	121
C ₄	3	14
:D _m 4 =		

CAMBER	
+	20
-	



A ₂	170	120
B ₂	170	174
C ₆		
:D _m 4 =		

CAMBER	
+	30
-	




A ₁	132	124
B ₁	129	139
C ₃	3	25
:D _m 5 =		

CAMBER	
+	20
-	


A ₁	130	92
B ₁	127	142
C ₅	3	50
:D _m 5 =		

CAMBER	
+	30
-	



A ₂	129	175
B ₂	170	122
C ₄	1	13
:D _m 5 =		

CAMBER	
+	30
-	



A ₂	120	171
B ₂	129	165
C ₆	3	16
:D _m 5 =		

CAMBER	
+	25
-	